NICHIA CORPORATION

SPECIFICATIONS FOR UV LED

NCSU276AT

- Pb-free Reflow Soldering Application
- Built-in ESD Protection Device
- RoHS Compliant



SPECIFICATIONS

(1) Absolute Maximum Ratings

Item	Symbol	Absolute Maximum Rating	Unit
Forward Current	\mathbf{I}_{F}	700	mA
Pulse Forward Current	I_{FP}	1000	mA
Allowable Reverse Current	I _R	85	mA
Power Dissipation	P _D	3.08	W
Operating Temperature	T _{opr}	-10~85	°C
Storage Temperature	T _{stg}	-40~100	°C
Junction Temperature	T,	90	°C

* Absolute Maximum Ratings at $T_s=25$ °C.

* $I_{\mbox{\scriptsize FP}}$ conditions with pulse width ${\leq}10\mbox{ms}$ and duty cycle ${\leq}10\%.$

(2) Initial Electrical/Optical Characteristics

It	em	Symbol	Condition	Тур	Max	Unit
	Forward Voltage	V _F	I _F =500mA	3.55	-	V
11405	Radiant Flux	Φ _e	I _F =500mA	950	-	mW
U405	Peak Wavelength	λ _p	I _F =500mA	405	-	nm
	Spectrum Half Width	Δλ	I _F =500mA	12	-	nm
	Forward Voltage	V _F	I _F =500mA	3.7	-	V
11205	Radiant Flux	Φ _e	I _F =500mA	900	-	mW
U385	Peak Wavelength	λp	I _F =500mA	385	-	nm
	Spectrum Half Width	Δλ	I _F =500mA	10	-	nm
	Forward Voltage	V _F	I _F =500mA	3.8	-	V
11265	Radiant Flux	Φe	I _F =500mA	780	-	mW
U365	Peak Wavelength	λ _p	I _F =500mA	365	-	nm
	Spectrum Half Width	Δλ	I _F =500mA	9	-	nm
Thermal Resistance		$R_{\theta JS}$	-	11.0	13.5	°C/W

* Characteristics at T_s =25°C.

* Radiant Flux value as per CIE 127:2007 standard.

* $R_{\theta JS}$ is Thermal Resistance from junction to T_S measuring point.

* It is recommended to operate the LEDs at a current greater than 10% of the sorting current to stabilize the LED characteristics.

RANKS

Item	Rank	Min	Max	Unit	
	H2	4.2	4.4		
	H1	4.0	4.2		
	M2	3.8	4.0		
Forward Voltage	M1	3.6	3.8	V	
	L2	3.4	3.6		
	L1	3.2	3.4		
	К2	3.0	3.2		
	P38d22	1175	1280		
	P38d21	1080	1175		
	P37d22	990	1080		
Radiant Flux	P37d21	910	990	mW	
	P36d22	835	910	IIIVV	
	P36d21	765	835		
	P35d22	700	765		
	P35d21	640	700		
	U405	400	410		
Peak Wavelength	U385	380	390	nm	
-	U365	360	370		

* Ranking at T_s=25°C.

* Forward Voltage Tolerance: ±0.05V

* Radiant Flux Tolerance: ±6%

* Peak Wavelength Tolerance: ±3nm

 \ast LEDs from the above ranks will be shipped.

The rank combination ratio per shipment will be decided by Nichia.

Radiant Flux Ranks by Peak Wavelength


Ranking by Radiant Flux Ranking by Peak Wavelength	P35d21	P35d22	P36d21	P36d22	P37d21	P37d22	P38d21	P38d22
U405								
U385								
U365								


OUTLINE DIMENSIONS


This product complies with RoHS Directive.


NCSU276A 管理番号 No. STS-DA7-5335

(単位 Unit: mm, 公差 Tolerance: ±0.2)











項目 Item	内容 Description
パッケージ材質	セラミックス
Package Materials	Ceramics
封止樹脂材質 Encapsulating Resin Materials	シリコーン樹脂 Silicone Resin
電極材質	金メッキ
Electrodes Materials	Au-plated
レンズ材質	シリコーン樹脂
Lens Materials	Silicone Resin
質量 Weight	0.034g (TYP)




SOLDERING

• Recommended Reflow Soldering Condition(Lead-free Solder)



• Recommended Soldering Pad Pattern



(単位 Unit: mm)

- * This LED is designed to be reflow soldered on to a PCB. If dip soldered or hand soldered, Nichia cannot guarantee its reliability.
- * Reflow soldering must not be performed more than twice.
- * Avoid rapid cooling. Ramp down the temperature gradually from the peak temperature.
- * Nitrogen reflow soldering is recommended. Air flow soldering conditions can cause optical degradation, caused by heat and/or atmosphere.
- * Since the silicone used in the encapsulating resin is soft, do not press on the encapsulant resin.


Pressure can cause nicks, chip-outs, encapsulant delamination and deformation, and wire breaks, decreasing reliability. When using automatic pick and place machine, use a pick up nozzle which does not directly apply stress to the encapsulation of the LEDs.


Recommended conditions:

Using a nozzle designed for the LEDs is recommended. (See Figure below)

 \ast The nozzle must not have any direct contact with the encapsulating resin.

Direct contact with the encapsulating resin may result in internal disconnections causing the LED not to illuminate.





Expansion of A


(単位 Unit: mm)

* Repairing should not be done after the LEDs have been soldered.

It should be confirmed beforehand whether the characteristics of the LEDs will or will not be damaged by repairing.


- st When soldering, do not apply stress to the LED while the LED is hot.
- * The recommended soldering pad pattern is designed for attachment of the LED without problems. When precise mounting accuracy is required, such as high-density mounting, ensure that the size and shape of the pad are suitable for the circuit design.
- * When flux is used, it should be a halogen free flux. Ensure that the manufacturing process is not designed in a manner where the flux will come in contact with the LEDs.
- * Make sure that there are no issues with the type and amount of solder that is being used.

TAPE AND REEL DIMENSIONS



PACKAGING - TAPE & REEL

シリカゲルとともにリールをアルミ防湿袋に入れ、熱シールにより封をします。 Reels are shipped with desiccants in heat-sealed moisture-proof bags. Nxxxxxx 管理番号 No. STS-DA7-1109B



- * 本製品はテーピングしたのち、輸送の衝撃から保護するためダンボールで梱包します。 Products shipped on tape and reel are packed in a moisture-proof bag. They are shipped in cardboard boxes to protect them from external forces during transportation.
- * 取り扱いに際して、落下させたり、強い衝撃を与えたりしますと、製品を損傷させる原因になりますので注意して下さい。
- Do not drop or expose the box to external forces as it may damage the products. * ダンボールには防水加工がされておりませんので、梱包箱が水に濡れないよう注意して下さい。
- Do not expose to water. The box is not water-resistant.
- * 輸送、運搬に際して弊社よりの梱包状態あるいは同等の梱包を行って下さい。 Using the original package material or equivalent in transit is recommended.

LOT NUMBERING CODE

Lot Number is presented by using the following alphanumeric code.

YMxxxx	-	RRR
--------	---	-----

Y - Year

Cui	
Year	Y
2013	D
2014	E
2015	F
2016	G
2017	Н
2018	Ι

M - Month


Month	М	Month	М
1	1	7	7
2	2	8	8
3	3	9	9
4	4	10	А
5	5	11	В
6	6	12	С

xxxx-Nichia's Product Number


RRR-Ranking by Wavelength, Ranking by Radiant Flux, Ranking by Forward Voltage

DERATING CHARACTERISTICS


NCSU276A 管理番号 No. STS-DA7-5336A



はんだ接合部温度(アノード側)-許容順電流特性 Solder Temperature(Anode Side) vs Allowable Forward Current



デューティー比-許容順電流特性 Duty Ratio vs Allowable Forward Current





OPTICAL CHARACTERISTICS

* 本特性は参考です。

All characteristics shown are for reference only and are not guaranteed.

NCSU276A 管理番号 No. STS-DA7-5728






* 本特性はピーク波長ランクU365に対応しています。 The graphs above show the characteristics for U365 LEDs of this product.


OPTICAL CHARACTERISTICS

* 本特性は参考です。

All characteristics shown are for reference only and are not guaranteed.

NCSU276A 管理番号 No. STS-DA7-5729






* 本特性はピーク波長ランクU385に対応しています。 The graphs above show the characteristics for U385 LEDs of this product.


OPTICAL CHARACTERISTICS

* 本特性は参考です。

All characteristics shown are for reference only and are not guaranteed.

NCSU276A 管理番号 No. STS-DA7-5730






The graphs above show the characteristics for U405 LEDs of this product.

* 本特性は参考です。

All characteristics shown are for reference only and are not guaranteed.

NCSU276A 管理番号 No. STS-DA7-5731




* 本特性はピーク波長ランクU365に対応しています。 The graphs above show the characteristics for U365 LEDs of this product.

* 本特性は参考です。

All characteristics shown are for reference only and are not guaranteed.

NCSU276A 管理番号 No. STS-DA7-5732




* 本特性はピーク波長ランクU385に対応しています。 The graphs above show the characteristics for U385 LEDs of this product.

* 本特性は参考です。

All characteristics shown are for reference only and are not guaranteed.

NCSU276A 管理番号 No. STS-DA7-5733




* 本特性はピーク波長ランクU405に対応しています。 The graphs above show the characteristics for U405 LEDs of this product.

* 本特性は参考です。

All characteristics shown are for reference only and are not guaranteed.

NCSU276A 管理番号 No. STS-DA7-5734




* 本特性はピーク波長ランクU365に対応しています。
 The graphs above show the characteristics for U365 LEDs of this product.

* 本特性は参考です。

All characteristics shown are for reference only and are not guaranteed.

NCSU276A 管理番号 No. STS-DA7-5735




* 本特性はピーク波長ランクU385に対応しています。 The graphs above show the characteristics for U385 LEDs of this product.

* 本特性は参考です。

All characteristics shown are for reference only and are not guaranteed.

NCSU276A 管理番号 No. STS-DA7-5736



* 本特性はピーク波長ランクU405に対応しています。
 The graphs above show the characteristics for U405 LEDs of this product.

RELIABILITY

(1) Tests and Results

Test	Reference Standard	Test Conditions	Test Duration	Failure Criteria #	Units Failed/Tested
Resistance to Soldering Heat (Reflow Soldering)	JEITA ED-4701 300 301	T _{sld} =260°C, 10sec, 2reflows, Precondition: 30°C, 70%RH, 168hr		#1	0/10
Temperature Cycle	JEITA ED-4701 100 105	-40°C(30min)~25°C(5min)~ 100°C(30min)~25°C(5min)	100cycles	#1	0/10
High Temperature Storage	JEITA ED-4701 200 201	T _A =100°C	1000hours	#1	0/10
Low Temperature Storage	JEITA ED-4701 200 202	T _A =-40°C	1000hours	#1	0/10
Room Temperature Operating Life		T _A =25°C, I _F =700mA	1000hours	#1	0/10
High Temperature Operating Life		T _A =85°C, I _F =60mA	1000hours	#1	0/10
Temperature Humidity Operating Life		60°C, RH=90%, I _F =350mA	500hours	#1	0/10
Low Temperature Operating Life		T _A =-10°C, I _F =500mA	1000hours	#1	0/10
Vibration	JEITA ED-4701 400 403	200m/s ² , 100~2000~100Hz, 4cycles, 4min, each X, Y, Z	48minutes	#1	0/10
Electrostatic Discharges	JEITA ED-4701 300 304	HBM, 2kV, 1.5k Ω , 100pF, 3pulses, alternately positive or negative		#1	0/10

NOTES:

1) R_{θJA}≈19.1°C/W

2) Measurements are performed after allowing the LEDs to return to room temperature.

(2) Failure Criteria

Criteria #	Items	Conditions	Failure Criteria
	Forward Voltage(V _F)	I _F =500mA	>Initial value×1.1
#1	Radiant Flux(Φ_E)	I _F =500mA	<initial td="" value×0.7<=""></initial>

CAUTIONS

(1) Storage

Conditions		Temperature	Humidity	Time
	Before Opening Aluminum Bag	≤30°C	≤90%RH	Within 1 Year from Delivery Date
Storage	After Opening Aluminum Bag	≤30°C	≤70%RH	≤168hours
Baking		65±5°C	-	≥24hours


• Product complies with JEDEC MSL 3 or equivalent. See IPC/JEDEC STD-020 for moisture-sensitivity details.

•	• Absorbed moisture in LED packages can vaporize and expand during soldering, which can cause interface delamination
	and result in optical performance degradation. Products are packed in moisture-proof aluminum bags
	to minimize moisture absorption during transportation and storage.
	Included silica gel desiccants change from blue to red if moisture had penetrated bags.

- After opening the moisture-proof aluminum bag, the products should go through the soldering process within the range of the conditions stated above. Unused remaining LEDs should be stored with silica gel desiccants in a hermetically sealed container, preferably the original moisture-proof bags for storage.
- After the "Period After Opening" storage time has been exceeded or silica gel desiccants are no longer blue, the products should be baked. Baking should only be done once.
- Although the leads or electrode pads (anode and cathode) of the product are plated with gold, prolonged exposure to a corrosive environment might cause the gold plated the leads or electrode pads to tarnish, and thus leading to difficulties in soldering. If unused LEDs remain, they must be stored in a hermetically sealed container. Nichia recommends using the original moisture-proof bag for storage.
- Do not use sulfur-containing materials in commercial products. Some materials, such as seals and adhesives, may contain sulfur. The contaminated plating of LEDs might cause an open circuit. Silicone rubber is recommended as a material for seals. Bear in mind, the use of silicones may lead to silicone contamination of electrical contacts inside the products, caused by low molecular weight volatile siloxane.
- To prevent water condensation, please avoid large temperature and humidity fluctuations for the storage conditions.
- Do not store the LEDs in a dusty environment.
- Do not expose the LEDs to direct sunlight and/or an environment where the temperature is higher than normal room temperature.

(2) Directions for Use

• When designing a circuit, the current through each LED must not exceed the Absolute Maximum Rating. Operating at a constant current per LED is recommended. In case of operating at a constant voltage, Circuit B is recommended. If the LEDs are operated with constant voltage using Circuit A, the current through the LEDs may vary due to the variation in Forward Voltage characteristics of the LEDs.



- This product should be operated using forward current. Ensure that the product is not subjected to either forward or reverse voltage while it is not in use. In particular, subjecting it to continuous reverse voltage may cause migration, which may cause damage to the LED die. When used in displays that are not used for a long time, the main power supply should be switched off for safety.
- It is recommended to operate the LEDs at a current greater than 10% of the sorting current to stabilize the LED characteristics.
- Ensure that excessive voltages such as lightning surges are not applied to the LEDs.
- For outdoor use, necessary measures should be taken to prevent water, moisture and salt air damage.
- This LED also emits visible light. Please take notice of visible light spectrum,
- in case you use this LED as light source of sensors etc.

(3) Handling Precautions

- Do not handle the LEDs with bare hands as it will contaminate the LED surface and may affect the optical characteristics: it might cause the LED to be deformed and/or the wire to break, which will cause the LED not to illuminate.
- When handling the product with tweezers, be careful not to apply excessive force to the resin.
- Otherwise, The resin can be cut, chipped, delaminate or deformed, causing wire-bond breaks and catastrophic failures. • Dropping the product may cause damage.
- Do not stack assembled PCBs together. Failure to comply can cause the resin portion of the product to be cut, chipped, delaminated and/or deformed. It may cause wire to break, leading to catastrophic failures.

(4) Design Consideration

- Although Nichia recommends using a copper PCB for this product, customer is advised to verify the PCB with the products before use. Stress during soldering can cause the glass lens to break and/or the solder joints to crack.
- PCB warpage after mounting the products onto a PCB can cause the package to break. The LED should be placed in a way to minimize the stress on the LEDs due to PCB bow and twist.
- The position and orientation of the LEDs affect how much mechanical stress is exerted on the LEDs placed near the score lines. The LED should be placed in a way to minimize the stress on the LEDs due to board flexing.
- Board separation must be performed using special jigs, not using hands.
- If an aluminum PCB is used, customer is advised to verify the PCB with the products before use. Thermal stress during use can cause the solder joints to crack.
- When substances commonly found in ink adhere to the resin of this product, it may reduce the radiant flux and may change the material properties. Materials, such as dustproof glass, should be used to protect the LEDs.

(5) Electrostatic Discharge (ESD)

- The products are sensitive to static electricity or surge voltage. ESD can damage a die and its reliability.
 - When handling the products, the following measures against electrostatic discharge are strongly recommended: Eliminating the charge
 - Grounded wrist strap, ESD footwear, clothes, and floors
 - Grounded workstation equipment and tools
 - ESD table/shelf mat made of conductive materials
- Ensure that tools, jigs and machines that are being used are properly grounded and that proper grounding techniques are used in work areas. For devices/equipment that mount the LEDs, protection against surge voltages should also be used.
- If tools or equipment contain insulating materials such as glass or plastic,
- the following measures against electrostatic discharge are strongly recommended:
 - Dissipating static charge with conductive materials
 - Preventing charge generation with moisture
 - Neutralizing the charge with ionizers
- The customer is advised to check if the LEDs are damaged by ESD when performing the characteristics inspection of the LEDs in the application.
 Damage can be detected with a forward voltage measurement at low current (≤1mA).
- ESD damaged LEDs may have current flow at a low voltage.

Failure Criteria: V_F <2.0V at I_F =0.5mA

(6) Thermal Management

- Proper thermal management is an important when designing products with LEDs. LED die temperature is affected by PCB thermal resistance and LED spacing on the board. Please design products in a way that the LED die temperature does not exceed the maximum Junction Temperature (T_J).
- Drive current should be determined for the surrounding ambient temperature (T_A) to dissipate the heat from the product.
- The following equations can be used to calculate the junction temperature of the products.

1) $T_J = T_A + R_{\theta JA} \cdot W$ 2) $T_J = T_S + R_{\theta JS} \cdot W$

*T_J=LED junction temperature: °C


T_A=Ambient temperature: °C

T_s=Soldering temperature (anode side): °C

 $R_{\theta JA}$ =Thermal resistance from junction to ambient: °C/W

 $R_{\mbox{\tiny \thetaJS}}\mbox{=}\mbox{Thermal resistance from junction to }T_{\mbox{\tiny S}}\mbox{ measuring point: }\mbox{°C/W}$

W=Input power($I_F \times V_F$): W



(7) Cleaning

- The LEDs should not be cleaned with water, benzine, and/or thinner.
- If required, isopropyl alcohol (IPA) should be used. Other solvents may cause premature failure to the LEDs due to the damage to the resin portion. The effects of such solvents should be verified prior to use. In addition, the use of CFCs such as Freon is heavily regulated.
- When dust and/or dirt adheres to the LEDs, soak a cloth with Isopropyl alcohol (IPA), then squeeze it before wiping the LEDs.
- Ultrasonic cleaning is not recommended since it may have adverse effects on the LEDs depending on the ultrasonic power and how LED is assembled.

If ultrasonic cleaning must be used, the customer is advised to make sure the LEDs will not be damaged prior to cleaning.

(8) Eye Safety

• In 2006, the International Electrical Commission (IEC) published IEC 62471:2006 Photobiological safety of lamps and lamp systems, which added LEDs in its scope.

On the other hand, the IEC 60825-1:2007 laser safety standard removed LEDs from its scope. However, please be advised that some countries and regions have adopted standards based on the IEC laser safety standard IEC 60825-1:20112001, which still includes LEDs in its scope. Most of Nichia's LEDs can be classified as belonging into either the Exempt Group or Risk Group 1. High-power LEDs, that emit light containing blue wavelengths, may be classified as Risk Group 2. Please proceed with caution when viewing directly any LEDs driven at high current, or viewing LEDs with optical instruments which may greatly increase the damages to your eyes.

- Viewing a flashing light may cause eye discomfort. When incorporating the LED into your product, please be careful to avoid adverse effects on the human body caused by light stimulation.
- The products are UV light LEDs, and radiate intense UV light during operation. Since UV light can be harmful to eyes, do NOT look directly into the UV light, even through an optical instrument. In case of the light reflection, UV protective glasses are required to use in order to avoid damage by the light.

(9) Others

- The LEDs described in this brochure are intended to be used for ordinary electronic equipment (such as office equipment, communications equipment, measurement instruments and household appliances).
 Consult Nichia's sales staff in advance for information on the applications in which exceptional quality and reliability are required, particularly when the failure or malfunction of the LEDs may directly jeopardize life or health (such as for airplanes, aerospace, submersible repeaters, nuclear reactor control system, automobiles, traffic control equipment, life support systems and safety devices).
- The customer shall not reverse engineer by disassembling or analysis of the LEDs without having prior written consent from Nichia. When defective LEDs are found, the customer shall inform Nichia directly before disassembling or analysis.
- The specifications and appearance of this product may change without notice; Nichia does not guarantee the contents of this specification. Both the customer and Nichia will agree on the official specifications of supplied products before the volume production of a program begins.

Mounting Techniques for LEDs with a Lens

1. Introduction

As LEDs have recently been miniaturized and highly-functional, higher mounting technologies are necessary for them. It has been difficult to mount such advanced LEDs because of the lenses and the smaller absorption area. Improper mounting will affect the function and the reliability of the performance from the end product. To manufacture high-performance lighting fixtures with high functional LEDs, it is critical to develop the mounting technology.

We have seen many mounting problems in highly-functional LEDs with a lens. This document provides the mounting techniques for such LEDs, exhibiting some mounting failures. Please note that this document recommends a modular mounter to be used.



2. Mounting Failures in LEDs with a Lens

Many LEDs with a lens have been developed for higher performance. Such lenses are mostly made of resin; when external stress is applied to the lens, some are susceptible to damage, leading to abnormal optical characteristics, and others are susceptible to wire breakage, leading to abnormal electrical characteristics. Therefore, applying external stress to the lens has to be avoided as much as possible.

Moreover, the contact area of a pick-and-place nozzle and the lens is limited by the presence of the lens, which sometimes causes air leak, resulting in absorption error.

Problem 1:	Damage to the lens during the mounting process
Problem 2:	Absorption error due to air leak

An LED lens sometimes sticks to the top cover tape due to the resin's adhesive property, resulting in LED tilting within the cavity.

Also, the center of gravity of an LED with a lens is located higher. When the emboss carrier tape is exposed to an excessive vibration, the LED may be tilted within the cavity.

- Problem 3: LED tilting within the cavity due to its adhesion to the top cover tape
- Problem 4: LED tilting within the cavity due to vibration of the emboss carrier tape

Please refer to the following sheets for the countermeasures against Problems 1 to 4.

NICHIA Application Note

3. Mounting Techniques


3-1. Problem 1: Damage to the lens during the mounting process

Nichia establishes the optimal absorption method and the optimal cavity shape/size for each LED with a lens.

In general, there are two absorption methods; one is the "nozzle insertion system" and the other is the "non-insertion nozzle system."

3-1-1. Nozzle Insertion System

The nozzle insertion system is optimal for the 383/385 series, considering the LED shape/tolerance and the cavity shape/size. The LEDs can be absorbed in a stable condition, when the nozzle is inserted into the cavity and brought close to the lens. Please take care not to insert the nozzle too close to the lens. Therefore, please refer to Nichia's specifications for the insertion depth.



The pick-and-place nozzle is chamfered so as to form a "C Surface" (a sloped surface) and an "R Surface" (a curved surface), enabling a smooth mounting of the LEDs. Such design of the nozzle can prevent the LEDs from tilting in the cavities.

3-1-2. Non-Insertion Nozzle System

When the nozzle insertion system is used for the x19 series, the nozzle may touch the lens and apply excessive stress to it, considering the LED's shape/tolerance and the dimensional tolerance of the nozzle. If the clearance is left between the nozzle and the lens to avoid the contact with each other, it may be impossible to insert the nozzle into the cavity due to the oversized nozzle.


Then, Nichia recommends that the "Non-Insertion Nozzle system" be used for the x19 series. With this system, the nozzle reaches at the top surface of the cavity and absorbs the LEDs.

With the nozzle insertion system, the lens can get damaged due to the insertion pressure of the nozzle. On the other hand, with the non-insertion nozzle system, the nozzle is less likely to apply stress to the lens; only a slight absorption stress is applied to the lens.

Also, superior durability of the nozzle is achieved because of its sufficient thickness, since it does not have to be inserted into the cavities.


ΜΝΙCΗΙΛ

Application Note




Correction of the Absorption Point

Please adjust the mounter to ensure that the nozzle should absorb the correct point on the LEDs. The absorption point can be corrected with the image recognition unit by aiming at the center of the hole on the bottom surface of the cavity. Please refer to the following pictures for the image recognition unit.



for ref. Panasonic CM Mounter



3-2. Problem 2: Absorption error due to air leak

By the presence of the lens, the contact area of a pick-and-place nozzle and the lens is limited, which sometimes causes air leak, resulting in absorption error. In such cases, please change the absorption power into a more appropriate value. Judging from Nichia's evaluation results, the LEDs can be properly mounted by adjusting the absorption power from -40 to -90 kpa.

3-3. Problem 3: LED tilting within the cavity due to its adhesion to the top cover tape


LED lenses are made of resin. Therefore, the lenses sometimes adhere to the top cover tape due to the resin's stickiness. When the cover tape is peeled from the carrier tape, the LEDs tilt within their cavities, resulting in mounting failure.

It is impossible to eliminate the stickiness of the lens. Please refer to the following pages for the countermeasures against the LED tilting.

NICHIA Application Note


3-3-1. Slow down the feeding speed.


When the feeding speed is fast, the pick-and-place nozzle absorbs the LED before the lens is detached from the top cover tape, resulting in mounting failure.




Even when the LED is in contact with the top cover tape; however, by lowering the feeding speed, it can be detached from the tape before absorbed by the nozzle.

In case of Low Feeding Speed





The LED can be detached from the top cover tape.



The nozzle can appropriately pick and place the LED.

For example, the feeding speed can be changed by the screen as follows:

ALL Machine CM 一速度データ	M20x Serie	s CM30	1 Series	OtherMa	achine
認識スピード	〇自動	〇高	速 💿	中速	○ 低速
マウントスピート	O 100	O 80	⊙ 60	O 40	O 20
吸着スピード	O 100	O 80	● 60	O 40	O 20
ータイマーデーター					
吸着保持延長	○ 標準	C	2倍	۲	4倍
実装保持延長	○ 標準	C)2倍	۰	4倍
フィータ駆動時間	○ 標準	C)中速	۲	低速

道目 餔 補正グループ A チッフ 部品 B 補正タイプ 標準チップ 特殊/スル B(タ(7530E)) 使用ノズル 部品供給形態 7-7 -ダータイン ブ種類 12mm7-7 送りビ 通常 **.** 廃棄方法 日 リトライ回数 10% データベース番号 10% 21 ON. 50% 100

for ref. Panasonic CM Mounter

for ref. Yamaha YS Mounter


NICHIA Application Note

で 次14名: で 次14番号:		MPSW03	6L.			60 C C	
速度xx:	3		速度(2	3	C	
吸着動作n"外少		1:1段	F階/1号	上昇	+		
装着動作か"外")		2.2/2/1/2上科			-	-	
@栗(11)							
方向;	0.0	j*.		-			
868U	0.1	宛朝的 [-	De-		

* It is impossible to change the feeding speed of Panasonic BM Mounter. Instead, the operation speed of the head can be lowered, lengthening the absorption pitch.

3-3-2. Change the peeling angle.


As the following figures show, when the top cover tape is peeled off from the emboss carrier tape in an acute angle, the LED can be easily detached from the top cover tape, preventing it from tilting within the cavity.



Peeling Angle: Obtuse

Peeling Angle: Acute

The peeling angle can be adjusted to its optimal value by some of the mounters as follows:



for ref. Panasonic CM Mounter

ΝΙCΗΙΛ **Application Note**

3-4. Problem 4: LED tilting within the cavity due to vibration of the emboss carrier tape

When an excessive vibration is applied to the emboss carrier tape, LEDs may tilt within the cavities.


LEDs with a lens are susceptible to vibration, resulting in tilting, since its center of gravity is located higher.

3-4-1. Slow down the feeding speed.

The higher the feeding speed is, the more the vibration affects the LEDs within the cavities. When LEDs tilt within the cavities, please lower the feeding speed to decrease the vibration.


(For ref. Nichia recommends that the feeding speed should be a little slower than high speed.)

The carrier tape may be vibrated by an air feeder much more than an electric feeder. Please select the feeder depending on the LEDs to ensure that they are properly mounted.



Higher Feeding Speed

The LED stays in a stable condition.




Lower Feeding Speed

3-4-2. Change the peeling point.


When the top cover tape is peeled off from the emboss carrier tape long before the nozzle comes down to absorb an LED, some of the LEDs move around within the space between the feeder cover and the carrier tape, leading to LED tilting.

Please peel off the cover tape just before the nozzle comes down to absorb an LED. Then, LED's up-and-down movement can be restricted, preventing from LED tilting.




New Peeling Position

Application Note



for ref. Panasonic CM Mounter

for ref. Yamaha YS Mounter



for ref. Panasonic BM Mounter

Comparison of the Peeling Positions

* Please note that some of the mounters are equipped with a shutter. In such cases, it is impossible to change the peeling position of the top cover tape.

ΜΝΙCΗΙΛ


Application Note

4. Caution

Please refrain from splicing the tape together.

"Splicing" stands for the tape joint process while the mounter is operated. When there are a few LEDs left on the reel which is loaded on the mounter, some customers cut off and joint the edge of the tape to the next tape without detaching the feeder from the device. The splicing is to raise the machine utilization without bringing the device to a halt.

The splicing, however, may lead to the LED mounting failure; the LEDs may be tilted within the cavities due to the external stress applied to the carrier tape.



Splicing

5. Notice

Some mounting techniques for LEDs with a lens are described herein; however, they don't fit in with all the mounters. Please select the optimal mounting techniques depending on the LED model and the mounter. Nichia will aim to continue collecting data concerning the mounting techniques and offering beneficial information to our customers.

When you are concerned about any mounting technique, please contact us.

We would appreciate your cooperation.